

ECS Configuration Change Request

1. Originator Sarah Lewallen	2. Log Date: 03/22/02	3. CCR #: 02-0246	4. Rev: —	5. Tel: 301-925-0865	6. Rm #: 2117B	7. Dept. SED
8. CCR Title: Add additional RAID on e0acg11,e0drg11, and e0icg11.						
9. Originator Signature/Date Sarah Lewallen /s/ 3/22/02			10. Class II	11. Type: CCR	12. Need Date: 4/30/02	
13. Office Manager Signature/Date Jim Mather /s/ 3/22/02			14. Category of Change: Update ECS Baseline Doc.		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted:			17. Schedule Impact: none	18. CI(s) Affected: DRPHW,ACMHW, ICLHW		
19. Release Affected by this Change: 6A, 6B		20. Date due to Customer: 4/30/02		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input checked="" type="checkbox"/> Other: E-MAIL FROM WAYNE HANSON (SEE NEXT SHEET)						
23. Problem: (use additional Sheets if necessary) Would like to redistribute the RAID purchased on SWGD to other systems that would better meet the needs of the DAAC.						
24. Proposed Solution: (use additional sheets if necessary) Remove 4 FC HBA from e0drg12. Install 2 FC HBA in e0acg11 and connect 2 SPs with 40x36GB of RAID. Configure 20x36 for browse and 20x36 for ftp_pull. Install 2 FC HBA in e0drg11 and connect 2 SPs with 20x36 for amasscache Install one SCSI HBA in e0icg11 and attach 20x9 SCSI RAID for increase in the buffer area to support cross daac data transfer.						
25. Alternate Solution: (use additional sheets if necessary) None						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Additional space will not be available where needed.						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input type="checkbox"/> PVC <input type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. EDF/SCDV CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. M&O CCB Chair (Sign/Date): Gary Gavigan /s/ 3/26/02			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

ADDITIONAL SHEET

CCR #: 02-0246 Rev: — Originator: Sarah Lewallen

Telephone: 301-925-0865 **Office:** 2117B

Title of Change: Add additional RAID on e0acg11,e0drg11, and e0icg11.

Clip from e-mail request from Wayne Hanson:

As a follow up to our telephone conversation on Friday, here is the EDC view on the best use of SGI fiber channel RAID purchased under SWGD.

1.44 TB attached to drg12 to bring the AMASS cache area up to 2TB.

540 GB attached to drg12 to increase the L0 buffer.

540 GB attached to acg11 to allow all of the browse images to exist on spinning media.

720 GB attached to acg11 to increase the size of the ftp pull area. This will lengthen the time distribution products are available to the customer for pick-up to 6-7 days at the present rate of distribution.

180 GB attached to icg11 to support the new cross DAAC data transfer.

540 GB attached to drg11 to decrease the number of tape accesses and to speed up file retrieval for Landsat 7 distribution. This would also allow us to designate more resources to the test mode to allow better testing in those modes.

Wayne